

### MISCELLANEOUS CME SERVICES: K47418

**CLIENT:** CLAYTON PROPERTIES GROUP, INC.  
DBA SUMMIT HOMES  
120 SE 30TH ST  
LEE'S SUMMIT, MO 64082

**REPORT NO:** K47418  
**REPORT DATE:** 7/15/2022  
**SERVICE DATE:** 7/12/2022

**PROJECT:** R20-21-214  
OSAGE 3RD PLAT

**AUTHORIZATION:**  
**CONTRACTOR:**

#### SERVICES:

Visited site as scheduled for observation of wall construction. Arrived on site as contractor was finishing up placement of Geogrid at level at 1052.67'. The contractor compacted 3/4" clean gravel in the reinforced section of the wall from 1052.67' to 1053.33', making 3 passes with a vibratory plate. The construction observed was in general accordance with wall plans reviewed at the site. KCTE did not observe the previous construction below 1052.67.

**TECHNICIAN:** JOHN KULAK  
ENGINEERING TECHNICIAN

**REPORT DISTRIBUTION:**  
HANNAH  
TRAVIS RUF  
DIANA JOHNSON

KANSAS CITY TESTING & ENGINEERING, LLC,



---

JIM BYRNES, R.G.  
PROJECT MANAGER