



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20223205, Public Works Right of Way Permit
Address: 4412 SW TANZANITE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|------------------------------|-------------|----------|------------------------|
| Site Visit Inspection | Matt Munger | Passed | Tuesday, July 26, 2022 |

| Corrective Action Required | |
|---|------|
| 1 | Misc |
| Site Visit - The drop has been installed. | |

Comments: