## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063

(816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20215273

Address: 3691 NE AKIN DR, Unit:B, LEES SUMMIT, MO 640643691 NE AKIN DR, Unit:C, LEES SUMMIT, MO

640643691 NE AKIN DR, Unit:D, LEES SUMMIT, MO 640643691 NE AKIN DR, Unit:A,

LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Commercial

Mark Harding

Failed

Thursday, August 04,

2022

Corrective Action Required:

1 Misc Support all gas piping Csst per code.

UNIT A:

-Nail all holes of corner truss hangers above rear bedroom and master

bathroom UNIT B:

-Remove bonding screw from neutral bus bar

-Protect plumbing at rear bathroom

-Plumbing vent cannot be located within 4 ft of firewall - repair plywood...

-Replace gas test pressure gauge. Needle not moving when pressure is released

-Support vent in attic. FYI: wall needs to be rocked

UNIT C: UNIT D:

-Nail all holes of corner truss hangers above rear bedroom and master

bathroom

## **Comments:**