

## **Third Party Inspection Report**

Inspector	Date							
David P. Ainsworth, P.E.		7:15 PM						
	8-15-22							
Company  David P. Ainemath, P. E.	Permit #	Permit Holder						
David P. Ainsworth, P.E.	2022-3031	Trumark						
Inspection Type	Address Woopside RIDGE LOT 163							
STRUCTURAL SLAB	362 NW PATCH CT. LSMO							
E-Mail Address dainsworth@chelepis.com		, , , ,						
Instructions: This form must be con	npleted when performing a third pa	erty inspection for any building						
<b>Instructions:</b> This form must be completed when performing a third party inspection for any building permit in Lee's Summit. Submit form within 48 hours after inspection to the Development Services								
Department. If a subsequent inspection that inspection being scheduled.	n is performed by the City, this form	n must be submitted prior to						
Check all boxes that apply to the site conditions and the inspection being performed.								
Site Conditions:								
Plans stamped by the City on si	te with the plot plan included. (Cop	ied plans are not acceptable)						
Erosion controls in place and maintained								
*Note: If these requirements are not met no inspection shall be performed or accepted by the City.								
Foundations and Footings:								
Foundation type and MBOE is equal to or above the plot plan								
Concrete encased electrode (ufer) ground installed (Location must be noted in comments)								
	ity Code requirements and matches							
Foundation Walls:								
Elevation is sufficient to achieve	2% slope away from structure							
No openings below the MBOE								
Concrete encased electrode (uf	Concrete encased electrode (ufer) ground exposed							
Foundation wall meets all City Code requirements and matches City approved plans or engineered design.								



F	r	a	ľ	n	i	n	g	
-	70		~		•		<b>~</b>	•

Framing meets all City Code requirements and matches City approved plans or engineered design.

\*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been passed.

## **Corrective Actions and Comments:**

STRUCTURAL SLABS WERE PROPERLY FORMED WITH NECESSARY SUPPORT FRANKING BELOW. REINFORCING STEEL WAS PROPERLY INSTALLED.

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both accurate and true.

Signature:

P. Clinaratt, P.E.

**Engineer/Architect Seal**