

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20221791
Address: 4717 NE JAMESTOWN DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyen	Failed	Friday, August 19, 2022

Corrective Action Required:

1	Miscellaneous Correction	-Fire block basement half bathroom wall from ceiling **bathroom wall still open to ceiling space, since the blockings are not installed flushed to stud face -Fire block top of chase basement tub from soffit and joist space **fb gaps
---	--------------------------	---

Comments: