

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20215273

Address: 3691 NE AKIN DR, Unit:B, LEES SUMMIT, MO 640643691 NE AKIN DR, Unit:C, LEES SUMMIT, MO
640643691 NE AKIN DR, Unit:D, LEES SUMMIT, MO 640643691 NE AKIN DR, Unit:A, LEES
SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|----------------------------------|--------------|----------|----------------------------|
| Rated Assembly Inspection | Khanh Nguyen | Partial | Monday, August 22, 2022 |

Corrective Action Required:

| | | |
|---|------|---|
| 1 | Misc | Attic separation wall-2nd layer OK Dwelling separation-2nd layer OK |
| | | -Fire caulk penetrations at I beam. Fully caulking around penetrations -Close excessive gap between FlameBlock sheathings located within 4 ft of firewall |

Comments: