



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20223634, Public Works Right of Way Permit  
Address: 1713 SW 27TH ST, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

| Inspection:                  | Inspector:  | Outcome: | Date:                     |
|------------------------------|-------------|----------|---------------------------|
| <b>Site Visit Inspection</b> | Matt Munger | Passed   | Thursday, August 25, 2022 |

|                            |   |
|----------------------------|---|
| Corrective Action Required |   |
| 1      Misc                | Site Visit - The work has been completed. AT&T was onsite with their trailers setting up to splice in the line. |

|                              |             |        |                           |
|------------------------------|-------------|--------|---------------------------|
| <b>Site Visit Inspection</b> | Matt Munger | Passed | Thursday, August 25, 2022 |
|------------------------------|-------------|--------|---------------------------|

|                            |                              |
|----------------------------|------------------------------|
| Corrective Action Required |                              |
| 1      Misc                | The work has been completed. |

**Comments:**