

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Permit #:PRPWRW20223242, Public Works Right of Way Permit Address: 2011 SW OSAGE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Site Visit Inspection Matt Munger Partial Tuesday, August 30, 2022

Corrective Action Required

1 Misc Site Visit - AT&T was onsite splicing in a temp line. he line has

not been installed yet.

**Comments:**