

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20215017  
Address: 126 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Shawn Hoffman	Failed	Friday, September 09, 2022

Corrective Action Required:

- |   |                          |   |
|---|--------------------------|---|
| 1 | Miscellaneous Correction | <ul style="list-style-type: none"><li>- Provide roof boot at DWV owner entry</li><li>- Address over notched hip rafter north east corner dining room</li><li>- Solid block sheathing breaks at bay window dining room</li><li>- Nail off joist hangers in living room doubles</li><li>- Complete gas connections at fire place</li><li>- Support gas line at fire place</li><li>- Collar ties at ridge above entry door</li><li>- No support for hip rafter above laundry</li><li>- Pan out switch box in return air space master bedroom</li><li>- Solid block sheathing breaks master bedroom at deck</li><li>- Address gap bay windows master bedroom south center</li><li>- Repair broken window master bedroom</li><li>- Address over notched stud basement right of north east window</li><li>- Fire block top of fur out north wall basement</li><li>- Provide support for soffit over 4' wide basement</li><li>- Provide clearance electrical at can light bottom of stairs</li><li>- Protect electrical panel from DWV above</li><li>- Flashing and trim all windows</li></ul> |
|---|--------------------------|---|

**Comments:**