



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20223212, Public Works Right of Way Permit

Address: 501 NE WENONGA PL, LEES SUMMIT, MO 64064500 NE WENONGA PL, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Nick Scott	Passed	Friday, September 16, 2022

Corrective Action Required

1	Misc	site visited and it appears work is complete passed
---	------	---

Comments: