



Professional Service Industries, Inc.  
2828 South 44th Street  
Kansas City, KS 66106

Phone: (913) 310-1600  
Fax: (913) 310-1601

Report No: FC:03533627-30

Issue No: 1

## Concrete Field Report

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: William Odell (Senior Project Manager)  
Date of Issue: 8/4/2022

**Client:** CORE STATES GROUP  
3039 PREMIERE PARKWAY, SUITE  
700  
DULUTH, GA 30097

**CC:** C FAIRBANKS  
CHRIS DIAMOND  
GREG HELLBUSCH  
J SANCHAZ  
JOSE SANCHEZ  
L MCKINZY  
S KESHETTY  
SUNIL DUBEY

**Project:** CHASE BANK-LEE'S SUMMIT  
LEE'S SUMMIT, MO

### General Field Data

**Technician:** Andrew Amy

**Test Date:** 8/3/2022

**Weather:** Rain

### Test Results

Set No.	# Spec.	Ticket	Batch Time	Unload Time	Cubic Yards Placed	Slump (in)	Air Content (%)	Air Temp. (°F)	Concrete Temp. (°F)
03533627-30-C1	5	861047	12:30	13:15	10.0	4.00	5.0	82	85

### Location & Remarks

**General Location:** North side curb

Set No.	Location	Remarks
03533627-30-C1	Northwest corner	

### Mix Data

Set No.	Supplier	Mix	Design Strength (psi)
03533627-30-C1	Geiger Ready-Mix	KCMMB 4K	4000

### Notes

1. Applicable ASTM standards unless otherwise indicated: Slump: C143; Air Content: C231; Temperature: C1064; Sampling: C172; Unit Weight: C138;  
2. Specimen(s) prepared to ASTM C 31

### Remarks