ntertek			Professional Service Industries, Inc. 2828 South 44th Street			Report No: FC:03533627-59			
			Kansas City,						Issue No: 1
Phone: (913) 310. Fax: (913) 310-16 Concrete Field Report					no exe no no	These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced except in full, without written permission by Professional Service Industries, Inc. If non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.			
Client: CORE 3039 F 700 DULU Project: CHAS	E STATES (PREMIERE TH, GA 3	GROUP PARKWAY 0097 EE'S SUMM	CC: 7, SUITE	C FAIRBANKS CHRIS DIAMOND GREG HELLBUSCI J SANCHAZ JOSE SANCHEZ L MCKINZY S KESHETTY SUNIL DUBEY	Н		atory: William Odell (S	Source renior Project Manager)	U
General Fie Technician: Chris	Erickson					Date of Issue:	9/15/2022		
General Fie Technician: Chris Test Date: 9/14/ Weather: Clear	Erickson 2022 -	Ticket	Batch Time	Unload Time	Cubic Yards			Air Temp. (°F)	Concrete
General Fie Technician: Chris Test Date: 9/14/ Weather: Clear Test Results Set No.	Erickson 2022 - S # Spec.		Batch Time		Placed	s Slump (in)	Air Content (%)	Air Temp. (°F)	Concrete Temp. (°F)
General Fie Technician: Chris Test Date: 9/14/ Weather: Clear Test Results	Erickson 2022 - S # Spec.	Ticket 864410	Batch Time	Unload Time			Air Content		
General Fie Technician: Chris Test Date: 9/14/ Weather: Clear Test Results Set No. 03533627-59-C1 Location &	Erickson 2022 S # Spec. 5 Remark : Curb Location	864410	09:48		Placed	s Slump (in)	Air Content (%)	Air Temp. (°F) 77	Temp. (°F
General Fie Technician: Chris Test Date: 9/14/. Weather: Clear Test Results Set No. 03533627-59-C1 Location & General Location Set No. 03533627-59-C1	Erickson 2022 S # Spec. 5 Remark : Curb Location	864410	09:48		Placed	s Slump (in)	Air Content (%) 4.5	Air Temp. (°F) 77	Temp. (°F
General Fie Technician: Chris Test Date: 9/14/ Weather: Clear Test Results Set No. 03533627-59-C1 Location & General Location Set No.	Erickson 2022 S # Spec. 5 Remark : Curb Location	864410	09:48		Placed 4.0	s Slump (in)	Air Content (%) 4.5 Rema	Air Temp. (°F) 77	Temp. (°F 81

Notes	Remarks
Applicable ASTM standards unless otherwise indicated: Slump: C143; Air Content: C231; Temperature: C1064; Sampling: C172; Unit Weight: C138; 2. Specimen(s) prepared to ASTM C 31 Sampled from Revolving Drum Truck Mixer (ASTM C 172, 5.2.3)	