

Client:

Professional Service Industries, Inc. 2828 South 44th Street Kansas City, KS 66106

Phone: (913) 310-1600 Fax: (913) 310-1601

C FAIRBANKS, CHRIS DIAMOND, GREG

JOSE SANCHEZ, L MCKINZY, S KESHETTY,

SUNIL DUBEY

HELLBUSCH, J SANCHAZ,

Report No: SDFR:03533627-21 Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

William Odell (Senior Project Manager) Approved Signatory: Date of Issue: 4/26/2022

Date: 4/22/2022

WEATHER: TEMPERATURE RANGE: PSI REPRESENTATIVE:

CC:

°F TO °F Kenneth Mathis

TYPE OF INSPECTION BEING PERFORMED	
SOILS	CONCRETE
☐ FOUNDATIONS	BATCH PLANT
CONTROLLED FILL (COMPACTION)	PLACEMENT (JOB SITE)
	SPECIMEN TRANSPORT
ASPHALT	OTHER
BATCH PLANT	
PLACEMENT (JOB SITE)	

BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

Summary Daily Field Report

CORE STATES GROUP

DULUTH, GA 30097

Project: CHASE BANK-LEE'S SUMMIT

LEE'S SUMMIT, MO

SUITE 700

3039 PREMIERE PARKWAY

As requested, a representative of PSI reported to the above referenced project site to retrieve one set of 5 cylinders cast by PSI which were transported back to the PSI laboratory for further curing and compressive strength testing.