

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20215037
Address: 428 NW KAYLEA CT, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Shawn Hoffman	Failed	Wednesday, September 21, 2022

Corrective Action Required:

1	Misc	- complete ductwork at basement bathroom vent - Strap DWV in basement bathroom - Air admittance valve is too low at basement bar sink. I would like to see this tied into vent system but not mandatory .
---	------	---

Comments: