## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20221788 Address: 4709 NE JAMESTOWN DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyen	Failed	Wednesday, September 21, 2022
Corrective Action Required: 1 Misc	**REMOVE TRASH AN -Submit footing inspe -Install windows and o -Install plywood at att -Frame load bearing w size -Insulate first, the soli -Bond gas piping -Fb middle basement -Over notched joist at -Seal all penetrations **Grounding connecti	ction from 3rd party doors ic wall above kitchen/r vall at stair or have eng d block cantilevered jo bedroom wall from sof pove middle basement of wall&ceiling return	naster bathroom wall ineer address the correct beam vists below fireplace fit bedroom
	inspection **OK TO INSULATE		

Comments: