CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063

(816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20216306

Address: 114 NW JOSHUA DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - Codes Michael Harkins Failed Thursday, September

Residential 29, 2022

Corrective Action Required:

2 Miscellaneous Provide cover attic access garage

Correction Install handrail basement

Tighten anti siphon device and shear pin at water shut off

Provide anchor bolts within 12" of plate break behind water heater

Provide deadbolt patio door

Provide joist hanger above patio door

Provide splash blocks 36" discharge from foundation

Provide 6" clearance to wood siding rear

(R317.1(5)

Seal gas line exterior penetration at meter

& sump

Seal top of exterior light fixtures

Lower meter can lid to grade maintain 14" - 16" meter to lid

Provide guardrail at front porch over 30" to grade

Remove silt deposits from curb inlet Clean sidewalks & street of mud & debris Provide 4 soffit vents covered patio per plan

Comments: