CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRSUBD20221459Address:3221 SW PERGOLA PARK DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
Grading/Excavation/Fill Inspection	Eric Sharp	Partial	Friday, October 07, 2022	
Informational: 1 Misc	Equipment delivered and minor grading done. 6/7/22 ES			
	No work being done today after last nights rain event. 6/8/22 ES			
	No work being done. 6/10/22 ES			
	Cook Flatt and Strobel engineers on site surveying. 6/13/22 ES			
	Michael from Bair Excavating was onsite relocating dirt. 6/14/22 ES			
	Bair Excavating on site grading site. 6/15/22 ES			
	Bair Excavating on site grading. Almost taken down the large mound of dirt. 6/16/22 ES			
	Bair Excavating on site gra	ding. 6/17/22 ES		
	Bair Excavating on site gra	ding. 6/20/22 ES		
	Bair excavating began grad 8/9/22	ding site area for off site se	wer install near MH A-2.	

Informational: 2 Misc	Bair Excavating onsite grading and preparing for sanitary install. 8/10/22 ES		
	Bair Excavating onsite grading and preparing more area for sanitary install. 8/11/22 ES		
	Bair Excavating onsite grading around entry to 5th plat. 8/18/22 ES		
	Bair Excavating continued grading area around entry into 5th plat. 8/18/22 ES		
	Bair Excavating grading around entry into 5th plat. 8/19/22 ES		
	Bair Excavating moving dirt from around entry to 5th plat over to west side of work area. 8/22/22 ES		
	Bair Excavating moving dirt with scraper and dozer around front entry to 5th plat. 8/23/22 ES		
	Bair Excavating moving dirt with scraper and dozer from east side to stockpile on west side. 8/24/22 ES		
	Bair Excavating pipe crew worked on backfilling areas along A line. Mike from CFS was onsite doing compaction testing. 9/9/22 ES		
	Troy's crew working on backfilling Sanitary line A and Adam's crew began backfilling Storm line 800 as well as the areas down towards the lake. Compacting with large roller. 9/28/22 ES		
	Adam's crew working on backfilling and compacting all storm lines as well as start of sanitary line B. 10/7/22 ES		

Comments: