

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20223554  
Address: 196 SW WINTER RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Pool Steel/Bonding - Residential</b>	Shawn Hoffman	Partial	Thursday, October 13, 2022

Corrective Action Required:

1	Misc	Bonding to 4 points to re-bar on shell 2 points of bonding on hot tub shell only
---	------	-------------------------------------------------------------------------------------

OK to pour shell

This is a partial inspection, schedule again when water bond, bonding ring, accessories, power cover, pumps are bonded.

**Comments:**