CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20215276 Address: 3675 NE AKIN DR, Unit:B, LEES SUMMIT, MO 640643675 NE AKIN DR, Unit:C, LEES SUMMIT, MO 640643675 NE AKIN DR, Unit:D, LEES SUMMIT, MO 640643675 NE AKIN DR, Unit:A, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
All Rough Inspection - Commercial		Khanh Nguyen	Failed	Monday, October 24, 2022	
Corrective A	ction Required:				
1 N	lisc	UNIT A:			
		Gap at vent roof flashing			
		-Raise the vent offset min 6" above sink flood rim at master bathroom			
		UNIT B: -Protect clothes washer red water line at wall bottom plate -The laundry/bathroom vent roof flashing not completely sealed around vent			
		UNIT C: -Protect plumbing at top wall plate at rear bathroom			
		UNIT D: -The laundry/bathroom ve	nt roof flashing not complet	ely sealed around vent	

Comments: