



---

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

---

Permit #:PRPWRW20225243, Public Works Right of Way Permit  
Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Partial	Tuesday, November 01, 2022

Corrective Action Required

1	Misc	Site Visit - No workers onsite, the work may have already been completed. I will check back.
---	------	--

**Comments:**