



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20224877, Public Works Right of Way Permit

Address: 2010 SW OSAGE DR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Passed	Wednesday, November 02, 2022

Corrective Action Required

1	Misc	Site Visit - The drop appears to have been completed.
---	------	---

**Comments:**