LEE'S SUMMIT

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20224249, Public Works Right of Way Permit Address: 207 SE DOUGLAS ST, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Partial	Monday, November 14, 2022
Corrective Action Requir 1 Misc	Site Vi the roa with o replace since t doing.	ite Visit - The workers were onsite, they are not working in the road but have a lane closed sign up. I stopped and spoke with one of the workers and let them know they would need eplace that sign with a different sign to not confuse drivers nce they are not closing a lane of traffic for the work they a oing. They said they would change it out. They are hugging	
	the should and have cones on the shoulder of the road. Monitoring.		e shoulder of the road.

Comments: