

2011 NW Topeka Blvd Topeka, Kansas 66608

785.270.6447

2121 Moodie Road Lawrence, Kansas 66046

785.856.9600

1100 W Cambridge Circle Drive

Suite 700

Kansas City, Kansas 66103

913.627.9040

DAILY FIELD REPORT

DAILITIE

CLIENT: NLV Development Company, LLC 3152 SW Grandstand Circle Lee's Summit, Missouri 64081 PROJECT: Pergola Park 5th Plat

Lee's Summit, MO

ATTN: Russell Pearson

WEATHER: Sunny / Windy

DATE: 10/13/22

CFS PERSONNEL: M. Capps

REPORT #: 22-5392-dr-21

DEVIATIONS

DEVIATION YES ☐ NO ✓

SOILS - COMPACTION MONITORING / TESTING

TEMPERATURE: 62

- · Monitored placement of compaction for utility trenches. Placement found to be in substantial compliance with project plans.
- · Field compaction tests performed for utility trenches
- · Fill found to be substantial compliance with project plans. Test results attached.