

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Permit #:PRPWRW20224249, Public Works Right of Way Permit Address: 207 SE DOUGLAS ST, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Site Visit Inspection Matt Munger Partial Wednesday, November 16,

2022

Corrective Action Required

1 Misc Site Visit - No workers were onsite at this time. The pits were

fenced off.

**Comments:**