CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
**DEVSERVICES.CITYOFLS.NET**

# Inspection Summary

Permit #: PRSUBD20224162
Address: 3221 SW PERGOLA PARK DR, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|---|---|---|---|
| **Grading/Excavation/Fill Inspection** | Eric Sharp | Partial | Friday, November 18, 2022 |

Informational:

| | | |
|---|---|---|
| 1 | Misc | Bair excavating onsite clearing trees/brush. 8/29/22 ES |
| | | Bair excavating onsite clearing trees/brush. 8/30/22 ES |
| | | Bair excavating onsite clearing trees/brush. 8/31/22 ES |
| | | Bair excavating onsite clearing trees/brush. 9/1/22 ES |
| | | Bair excavating started grading site. 9/2/22 ES |
| | | Bair excavating grading site. 9/6/22 ES |
| | | Bair excavating grading site. 9/7/22 ES |
| | | Bair excavating grading site. 9/8/22 ES |
| | | Bair Excavating grading site. 9/9/22 ES |
| | | Bair Excavating grading site and running sheepsfoot compactor along future roadway areas.s 9/12/22 ES |

No grading or excavating activities being performed. Delivered approved plans for Grading, MDP, Street and Storm to Adam. 9/26/22 ES

Adam's crew working on grading site. 10/7/22 ES

Bair crew working on grading site. Schlagel onsite verifying elevations on installed structures. 10/18/22 ES

Bair crew cutting slop from top of road surfaces from rain even early in week. 10/26/22 ES

Bair crew working on backfilling Sanitary trench line. pulled frozen top layer off and began filling with inner layers of backfill. 11/18/22 ES

**Comments:**