LEE'S SUMMIT

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20224249, Public Works Right of Way Permit Address: 207 SE DOUGLAS ST, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Site Visit Inspection		Matt Munger	Partial	Monday, November 21, 2022	
Corrective Action Required					
1	Misc		te Visit - No workers v nced off.	isit - No workers were onsite at this time. The pits were d off.	
Corrective Action Required					
		•	e are pits that are fenced off along 2nd street from Blue I to just east of Noel. No crews onsite.		

Comments: