
PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20225539, Public Works Right of Way Permit
Address: 4408 SW TANZANITE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Passed	Thursday, December 01, 2022

Corrective Action Required
1 Misc Site Visit - The drop appears to have been installed.

Comments: