



---

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

---

Permit #:PRPWRW20225553, Public Works Right of Way Permit

Address: 698 SE 3RD ST, LEES SUMMIT, MO 64063400 SE 3RD ST, LEES SUMMIT, MO 64063614 SE 4TH ST, LEES SUMMIT, MO 64063306 SE M 291 HWY, LEES SUMMIT, MO 64063408 SE 3RD ST, LEES SUMMIT, MO 64063410 SE 3RD ST, LEES SUMMIT, MO 64063517 SE 2ND ST, LEES SUMMIT, MO 64063521 SE 2ND ST, LEES SUMMIT, MO 64063529 SE 2ND ST, LEES SUMMIT, MO 64063300 SE 3RD ST, LEES SUMMIT, MO 64063

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

| Inspection:                  | Inspector:  | Outcome: | Date:                      |
|------------------------------|-------------|----------|----------------------------|
| <b>Site Visit Inspection</b> | Matt Munger | Partial  | Tuesday, December 06, 2022 |

### Corrective Action Required

|   |      |  |
|---|------|--|
| 1 | Misc | Site Visit - No workers onsite. There is an area that has been left that will need to be properly restored. I called Travis with Rock and Dirt and texted him the pictures. He is going to look into this. |
|---|------|--|

Note: My last inspection I had put notes in from SW 3rd which is not for this project.

### Comments: