



# LEE'S SUMMIT MISSOURI



## FIRE DEPARTMENT

### NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

BUSINESS NAME	CALIBER COLLISION		
ADDRESS	710 SE BLUE PKWY, LEES SUMMIT, MO 64063		
OWNER/OPERATOR NAME	Deerfield Construction Co Inc:	TELEPHONE	(513) 368-0979
ADDRESS	8960 Glendale Milford Rd Loveland, OH 45140 Primary: (513) 368-0979 Cell: <NO CELL PHONE>		

### EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1. _____	
2. _____	
3. _____	
4. _____	

### LOSS REDUCTION TYPE

<input type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: S-1	Map#:	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT #

### LOSS REDUCTION NARRATIVE

☐ NO VIOLATIONS NOTED

☐ ALL VIOLATIONS RESOLVED

Last Inspection

1st Inspection

2nd Inspection

3rd Inspection

4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Alarm Test	Craig Hill	Passed	Tuesday, December 06, 2022
Sprinkler - Hydrostatic Test	Jim Eden	Passed	Friday, September 30, 2022
Sprinkler - Flow Test	Craig Hill	Passed	Tuesday, December 06, 2022

Corrective Action Required:

- 1 Label Sprinkler Room Door  
Tag Sprinkler system.

**Fire Line - Hydrostatic Test**

Eric Sharp

Passed

Thursday, June 16, 2022

**Occupancy Inspection - Fire**

Craig Hill

Failed

Thursday, December 08, 2022

Corrective Action Required:

- 1 No address  
No in-service tag on the sprinkler system.

DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
December 08, 2022	Craig Hill	<input type="checkbox"/> Yes <input type="checkbox"/> No	