



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20225461, Public Works Right of Way Permit  
Address: 3725 SW WALSH DR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Passed	Tuesday, December 13, 2022

Corrective Action Required	
1      Misc	Site Visit - It appears the work has been completed. Closing.

**Comments:**