LEE'S SUMMIT

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20224249, Public Works Right of Way Permit Address: 207 SE DOUGLAS ST, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Partial	Tuesday, December 20, 2022
Corrective Action Requir 1 Misc	Site Vi were o alley o areas t furthe throug they a	disturbed. It appears they of city hall that they some they have attempted to re r attention. I will reach ou gh after the first of the yea re at with restoration. The	In straw over the areas that have a pit fenced off by the more work to do. Some of the store look like they may need t to Boley and setup a walk ir so we can establish where y will most likely need to e things are properly restored.

Comments: