

FIRE DEPARTMENT

NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

BUSINESS NAME	JOHN KNOX VILLAGE MEADOWS PHASE II - INDEPENDENT LIVING APARTMENTS		
ADDRESS	1801 NW OBRIEN RD, LEES SUMMIT, MO 64081520 NW HOPE LN, LEES SUMMIT, MO 64081		
OWNER/OPERATOR NAME	JOHN KNOX VILLAGE:	TELEPHONE	
ADDRESS	400 NW MURRAY RD LEES SUMMIT, MO 64081 Primary: Cell: <no cell="" phone=""></no>		

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1.	
2.	
3.	
4.	

LOSS REDUCTION TYPE

Occupancy 🔲 Ser	mi-Annual	Annual	Life Safety	Sprinkler	 Hazardous Material Permit
🔲 Complaint 🔲 Exp	olosive Storage	UST	Post-Incident	Open Burning	Other
CLASS:	Map#:	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT #
R-2					

LOSS REDUCTION NARRATIVE

NO VIOLATIONS NOTED			□ ALL VIOLATIONS RESOLVED			
Last Inspection	1st Inspection	2nd Inspection	3rd Inspection		4th Inspection	
INSPECTION	INSPECTOR	(OUTCOME	DATE		
Alarm Test	Craig Hill	F	Failed	Tuesday	/, December 13, 2022	
Corrective Action Required: 1 6 rooms did not have notification work Horn strobe for water flow did not ope Fire doors did not operate.		•				

Sprinkler - Hydrostatic Test	Craig Hill	Passed	Monday, November 21, 2022		
Sprinkler - Flow Test	Craig Hill	Passed	Tuesday, December 13, 2022		
	Craig Hill rop on alarm activation. er flow did not operate properly	Failed	Wednesday, December 14, 2022		
Alarm Test	Craig Hill	Passed	Thursday, December 15, 2022		
Occupancy Inspection - Fire Craig Hill Failed Monday, December 19, 2022 Corrective Action Required: 1 2030 master, closet, escutcheon 3028 laundry room sprinkler head missing. 3024 Laundry room sprinkler head missing EXIT signs					
Occupancy Inspection - Fire	Ben Hicks	Passed	Tuesday, December 20, 2022		
DATE OF REPORT December 20, 2022	INSPECTOR Ben Hicks	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNA TURE		