



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20225001, Public Works Right of Way Permit  
Address: 4400 SW TANZANITE CIR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Passed	Tuesday, December 20, 2022

Corrective Action Required

1	Misc	Site Visit - It appears the drop has been installed.
---	------	--

**Comments:**