



RE: JFE Woodside Ridge 134 Rough-In Inspection

That is adequate. Looks like a note that did not get updated. The 6(2x4)'s as installed are adequate

Chad M. Streeter, P.E.
Van Deurzen & Associates, P.A.
11011 King St., Ste. 130
Overland Park, Kansas 66210
Ph (913)451-6305
Fax (13) 451-1021
cmstreeter@vandeurzenassoc.com

See More





Cory Tworkowsky

To: Chad Streeter >

Monday



Woodside Ridge Lot 134 2151 NW Killarney Ln

Chad,

Inspector called me out on needing (5) 2x6s on ends of garage steel beam for support. I have (6) 2x4s currently. Is this sufficient or do I need to replace with 2x6s? Please let me know. Thanks!

10:24

