



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20225758, Public Works Right of Way Permit

Address: 2009 SW OSAGE DR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

| Inspection:                  | Inspector:  | Outcome: | Date:                    |
|------------------------------|-------------|----------|--------------------------|
| <b>Site Visit Inspection</b> | Matt Munger | Passed   | Monday, January 09, 2023 |

**Corrective Action Required**

|   |      |                                                      |
|---|------|------------------------------------------------------|
| 1 | Misc | Site Visit - It appears the drop has been installed. |
|---|------|------------------------------------------------------|

**Comments:**