



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20225491, Public Works Right of Way Permit
Address: 2011 SW OSAGE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Partial	Monday, January 09, 2023

Corrective Action Required	
1 Misc	Site Visit - The drop has not been installed yet and is running across several yards.

Comments: