

# FIRE DEPARTMENT

## NOTIFICATIONS/CONTACT INFORMATION SECTION

### PAGE 1

## 

BUSINESS NAME	THE LOCAL PIZZERIA			
ADDRESS	805 NE LAKEWOOD BLVD, LEES SUMMIT, MO 64064			
OWNER/OPERATOR NAME	H   D Architecture:	TELEPHONE		
ADDRESS	15225 Broadmoor St Overland Park, KS 66223 Primary: Cell: <no cell="" phone=""></no>			

## **EMERGENCY CONTACT INFORMATION**

NAME	TELEPHONE
1.	
2.	
3.	
4.	

## LOSS REDUCTION TYPE

🛾 Occupancy 🔲 Semi-Annual	🔲 Annual	Life Safety	Sprinkler	Hazardous Material Permit
🗋 Complaint 🛛 Explosive Storage	UST	Post-Incident	Open Burning	Other
CLASS: Map#:	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT #
-2				

### LOSS REDUCTION NARRATIVE

NO VIOLATIONS NOTED			LI ALL VIOLATIONS RESOLVED				
Last Inspection	1st Inspec	tion	2nd Inspection	3rd Ins	spection	4th Inspection	
INSPECTION		INSPECTOR		OUTCOME	DATE		
Alternate Protectio	n Systems	Craig Hill		Passed	Friday,	January 27, 2023	
Occupancy Inspect	ion - Fire	Ben Hicks		Failed	Thursda	ay, February 02, 2023	

Corrective Action Required:						
0,000	1 Emergency Exit lights not operational, front and rear					
Corrective Action Required:						
2 Emergency lighting	2 Emergency lighting not operational front and rear. Cieling lights shown on plans not seen.					
Corrective Action Required:						
3 Breaker box front pa	anel cover needs to be secured	in place				
Corrective Action Required:						
4 Multiple open electrical boxes needs cover plate installed in ceiling and around ansul fire suppression system						
Corrective Action Required:						
5 Filters need to in pla	ace over cooking aplliences whe	ere ansul syst	em installed			
Corrective Action Required:						
6 PLace address on back door						
DATE OF REPORT	INSPECTOR	PREVENTION FOR	DLLOW-UP	RESPONSIBLE SIGNA TURE		
February 02, 2023	Ben Hicks	□ Yes I	□ No			