



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20223654, Public Works Right of Way Permit
Address: 2011 SW OSAGE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Passed	Friday, February 03, 2023

Corrective Action Required

1	Misc	Site Visit - It appears the drop has been installed. 2017 still needs to be installed as the line runs across the driveway. There is a permit for 2017.
---	------	---

Comments: