



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20223242, Public Works Right of Way Permit  
Address: 2011 SW OSAGE DR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Passed	Friday, February 03, 2023

**Corrective Action Required**

1	Misc	Site Visit - It appears this has been installed. There is a line running to 2017 that has not been installed. There is a permit for that address.
---	------	---

**Comments:**