

FIRE DEPARTMENT

NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

| BUSINESS NAME | CRASH CHAMPIONS - PAINT BOOTH | | |
|---------------------|---|-----------|--|
| ADDRESS | 451 SE OLDHAM PKWY, Unit:B, LEES SUMMIT, MO 64081 | | |
| OWNER/OPERATOR NAME | MSE PROPERTY HOLDINGS GROUP, LLC: | TELEPHONE | |
| ADDRESS | 14330 S CICERO AVE CRESTWOOD, IL 60418 Primary: Cell: <no cell="" phone=""></no> | | |

EMERGENCY CONTACT INFORMATION

| NAME | TELEPHONE |
|------|-----------|
| 1. | |
| 2. | |
| 3. | |
| 4. | |

LOSS REDUCTION TYPE

| Occupancy 🔲 Ser | ni-Annual | Annual | Life Safety | Sprinkler | Hazardous Material Permit |
|-----------------|-----------------|--------|---------------|----------------|----------------------------------|
| Complaint 🛛 Exp | olosive Storage | UST | Post-Incident | Open Burning | Other |
| | Map#: | PFA#: | KNOX BOX: | KNOX LOCATION: | PERMIT # |
| N/A | | | | | |

LOSS REDUCTION NARRATIVE

| □ NO VIOLATIONS NOTED | | | □ ALL VIOLATIONS RESOLVED | | | |
|-----------------------|------------------------|----------------|---------------------------|-----------|-------------------|--|
| Last Inspection | 1st Inspection | 2nd Inspection | 3rd Inspe | ection | 4th Inspection | |
| | | | | | | |
| INSPECTION | INSPECTOR | O | UTCOME | DATE | | |
| Alarm Test | Craig Hill | Ν | ot Required | Wednesday | , August 10, 2022 | |
| Sprinkler - Hydros | static Test Craig Hill | N | ot Required | Wednesday | , August 10, 2022 | |

| Sprinkler - Flow Test | Craig Hill | Not Required | Wednesday, August 10, 2022 |
|--|--------------------|----------------------|----------------------------|
| Alternate Protection Systems Inspection | s Craig Hill | Passed | Wednesday, August 10, 2022 |
| Alternate Protection System Inspection | s Ben Hicks | Passed | Tuesday, February 07, 2023 |
| DATE OF REPORT | INSPECTOR | PREVENTION FOLLOW-UP | RESPONSIBLE SIGNA TURE |
| February 07, 2023 | Ben Hicks | REQUIRED? | |