

# David Mezger Engineering LLC

Tel: Cell 913-481-3774  
Office 816-736-4043

212 NE Circle Dr  
Kansas City, MO 64116

Email:  
mezgerde@gmail.com

**DME**

February 15, 2023

BeHome LLC

1101 SW 40<sup>th</sup> St.

Blue Springs, MO 64015

Re: Failed Inspection at 2035 SW Hook Farm Drive (Carter Plan)

Dear Sirs,

This letter is a follow up to the letter sent to you on January 16, 2023 outlining a procedure to correct the issues causing the failed inspection at the subject address. I have been forwarded a number of photographs by your Mr. Brian Ellis showing the implementation of the recommended repairs. It appears that although the Simpson Strong-Tie components used are not exactly the ones stated in my previous letter, they are equal or better and accomplish the result which I was wanting to achieve by increasing the hold-down capacity of the wall to the subfloor. I find this aspect of the repair to be acceptable. I have attached a copy of the previous letter along with the referenced photographs for use in resolving this issue with the permitting authority.

Sincerely,

David E. Mezger P.E.

