

Third Party Inspection Report

Inspector	Date	Time			
David P. Ainsworth, P.E.	4-19-23	10;00AM			
Company	Permit #	Permit Holder			
David P. Ainsworth, P.E.	2023-1491	McGRAW Homes			
Inspection Type	2023-1491 McGRAW HOMES Address PARK RIDGE LOT 391				
SOIL & FOOTING	SOIL & FOOTING 1524 NE PARK SPRINGS TER LSMO				
E-Mail Address dainsworth@chelepis.com					
Instructions: This form must be con	Instructions: This form must be completed when performing a third party inspection for any building				
permit in Lee's Summit. Submit form \	vithin 48 hours after inspection to t	he Development Services			
Department. If a subsequent inspection is performed by the City, this form must be submitted prior to					
that inspection being scheduled.					
Check all boxes that apply to the site conditions and the inspection being performed.					
Site Conditions:					
Plans stamped by the City on site with the plot plan included. (Copied plans are not acceptable)					
Erosion controls in place and maintained					
*Note: If these requirements are not met no inspection shall be performed or accepted by the City.					
Foundations and Footings:					
Foundation type and MBOE is equal to or above the plot plan					
Concrete encased electrode (ufer) ground installed (Location must be noted in comments)					
Foundation/Footing meets all City Code requirements and matches City approved plans or engineered design.					
Foundation Walls:					
Elevation is sufficient to achieve 2% slope away from structure					
No openings below the MBOE					
Concrete encased electrode (u	Concrete encased electrode (ufer) ground exposed				
Foundation wall meets all City Code requirements and matches City approved plans or engineered design.					



-				
H	ra	m	IIO	O.
8	I CI	8 8 8		g:

Framing meets all City Code requirements and matches City approved plans or engineered design.

*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been passed.

Corrective Actions and Comments:

UFER GROWND ROD IS LOCATED IN THE RIGHT SIDEWALL ABOUT 8' BACK OF THE RIGHT FRONT GORNER. SOIL BEARING CAPACITY WAS IN EXCESS OF 3,000 PSF

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both accurate and true.

Signature: Said Chinswatt

Engineer/Architect Seal