

Third Party Inspection Report

Inspector	Date	Time
David P. Ainsworth, P.E.	4-20-23	12:30 PM
Company	Permit #	Permit Holder
David P. Ainsworth, P.E.	2023-1588	CLAYTON PROPERTIES
Inspection Type	Address OSAGE LOT 71	
	2121 SLY RUTHE	RFORD DE LSMG
E-Mail Address dainsworth@chelepis.com		
Instructions: This form must be completed when performing a third party inspection for any building		

Instructions: This form must be completed when performing a third party inspection for any building permit in Lee's Summit. Submit form within 48 hours after inspection to the Development Services Department. If a subsequent inspection is performed by the City, this form must be submitted prior to that inspection being scheduled.

Check a	Ill boxes that apply to the site conditions and the inspection being performed.
Site C	onditions:
X	Plans stamped by the City on site with the plot plan included. (Copied plans are not acceptable)
X	Erosion controls in place and maintained
*Note:	If these requirements are not met no inspection shall be performed or accepted by the City.
Found	lations and Footings:
	Foundation type and MBOE is equal to or above the plot plan
	Concrete encased electrode (ufer) ground installed (Location must be noted in comments)
	Foundation/Footing meets all City Code requirements and matches City approved plans or engineered design.
Found	lation Walls:
X	Elevation is sufficient to achieve 2% slope away from structure
X	No openings below the MBOE
\times	Concrete encased electrode (ufer) ground exposed
	Foundation wall meets all City Code requirements and matches City approved plans or engineered design.

