

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20232292
Address: 1913 SW MERRYMAN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Kyle Beard	Failed	Thursday, June 08, 2023

Corrective Action Required:

1 Misc

- fire blocking between the wall that has the electrical panel and the two windows is over 10 feet in length
- Fire blocking in the wall is needed in the bedroom between the sewer chase and the exit window
- H&A high low needs to be sealed better (one hole is not sealed)

Comments: