



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20232883, Public Works Right of Way Permit
Address: 4408 SW TANZANITE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Partial	Monday, June 26, 2023

Corrective Action Required

1	Misc	Site Visit - There is a small amount of decorative rock in the road with cones around it in front of the homeowners driveway. No issues at this time.
---	------	---

Comments: