



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20232883, Public Works Right of Way Permit
Address: 4408 SW TANZANITE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Passed	Monday, July 10, 2023

Corrective Action Required

1	Misc	Site Visit - The rock pile was no longer there. Closing. If more rock is to be placed into the roadway, another permit will be required.
---	------	--

Comments: