

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20232292
Address: 1913 SW MERRYMAN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Final Building Inspection - Residential	Kyle Beard	Failed	Tuesday, July 18, 2023

Corrective Action Required:

- | | | |
|---|--------------------------|---|
| 1 | Miscellaneous Correction | <ul style="list-style-type: none">- Sump pump electrical outlet needs to state it is non GFCI protected- Bar electrical outlets are not fully installed- R314.3 states that a smoke alarm shall be located immediately outside of the vicinity of a bedroom and not less than 3 feet horizontally from a bathroom door unless this would prevent a placement of a smoke alarm |
|---|--------------------------|---|

Comments: