

Third Party Inspection Report

Inspector	Date	Time							
David P. Ainsworth, P.E.	8-11-23	101 00 AM							
Company	Permit #	Permit Holder							
David P. Ainsworth, P.E.	2023-3615 Address OSAGE LOTS 7	CLANTON PROPERTY							
Inspection Type	Address OSAGE LOTST	OSAGE DO LSMO							
FOOTING	2140 \$ 2142 SXI OSAGEDR LSMC								
E-Mail Address dainsworth@chelepis.co	m								
Instructions: This form must be completed when performing a third party inspection for any building									
permit in Lee's Summit. Submit form within 48 hours after inspection to the Development Services									
Department. If a subsequent inspection is performed by the City, this form must be submitted prior to									
that inspection being scheduled.									
Check all boxes that apply to the site conditions and the inspection being performed.									
Site Conditions:									
Plans stamped by the City on site with the plot plan included. (Copied plans are not acceptable)									
Evosion controls in place and maintained									
Erosion controls in place and n	naintained								
*Note: If these requirements are not met no inspection shall be performed or accepted by the City.									
Foundations and Footings:									
Foundation type and MBOE is equal to or above the plot plan									
Concrete encased electrode (ufer) ground installed (Location must be noted in comments)									
Foundation/Footing meets all City Code requirements and matches City approved plans or									
engineered design.									
Foundation Walls:									
Elevation is sufficient to achiev	ve 2% slope away from structure								
No openings below the MBOE									
Concrete encased electrode (ufer) ground exposed								
Foundation wall meets all City engineered design.	Code requirements and matches Ci	ty approved plans or							



-					d					
Þ	r	a	ľ	٦	٦	ı	ľ	٦	σ	0
	В	u	8	U	u	8	u	B	5	0

Framing meets all City Code requirements and matches City approved plans or engineered design.

*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been passed.

Corrective Actions and Comments:

UFER, GROUND RODS (2) ARE LOCATED IN THE REAR GARAGE WALLS ABOUT 4' EACH SIDE OF THE DUPLEY DEMISING WALLO

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both accurate and true.

Signature:

davill. Umanorek P.Z.

Engineer/Architect Seal

8-11-22