

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20231910  
Address: 2622 SW TRACKER LN, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Mitchell Schwarz	Failed	Monday, September 11, 2023

Corrective Action Required:  
2 Misc

- fire block owners bath tub floor
- fire block owners shower/owner's closet wall to ceiling space
- fire block beam ends throughout basement
- fire block dead space right of wet bar in basement
- provide support for furr down ceiling joist to floor joist above

Okay to insulate

**Comments:**