

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20224767
Address: 1100 NW MAIN ST, Unit:D, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|----------------------------------|------------|----------|---------------------------|
| Rated Assembly Inspection | Robb Popp | Partial | Tuesday, October 03, 2023 |

Corrective Action Required:

| | | |
|---|------|--|
| 1 | Misc | Demising wall screw pattern: -West side complete -East side complete -Riser room complete **Seal perimeter and all penetrations -West side only: Complete -East side: Seal in between bar joists at north (2) column lines -Riser room complete **INSTALL FIRE RATED JOINT SYSTEM PER IBC 715 THROUGHOUT |
|---|------|--|

Comments: